Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC. **Well Operator:** XTO ENERGY INC. **Well Name:** MARMON HAHN 44X-3

Field Name: HOFFLUND Well File #: 16328

Date Incident:11/9/2015Time Incident:08:03Facility ID Number:County:WILLIAMSTwp:154Rng:95Sec:3Qtr.

Location Description:

Submitted By: JORDAN WOLF Received By:

Contact Person: KAYLAN DIRKX

P.O Box 6506 321 22ND AVE E

WILLISTON, ND 58801

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 30 Gallons

Brine 2 Barrels 2 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None- spill was contained within the dirk tank berm.

Areal Extent:

Potential Environmental Impacts:

None-spill was contained within the dirk tank berm.

Action Taken or Planned:

A flowback vessel was placed on the well to control the production. The recovered fluids were hauled to a SWD. The recovered dirt and gravel will be removed and hauled to an approved waste disposal facility.

Wastes Disposal Location: Prairie Disposal

Agencies Involved:

Updates

Date: 11/10/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on the constructed well site according to the report. NDIC retains oversight.